

Ship Name:	APL CYPRINE	Ship Type:	Containership
IMO Number:	9139725	Flag:	Singapore
Date Detained:	04/12/2002	Class Society:	American Bureau of Shipping
Port:	Long Beach, California	Company(s):	<u>Owners, Operators or Managers</u> APL Cyprine

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	2020 - Fire drills	Crew not able to demonstrate proficiency in fire drill.
	2025 - Abandon ship drills	Crew not able to demonstrate proficiency in fire drill.

Ship Name:	AURORA 2	Ship Type:	Refrigerated Cargo Carrier
IMO Number:	8223488	Flag:	Republic of Korea
Date Detained:	04/17/2002	Class Society:	Korean Register of Shipping
Port:	Dutch Harbor, Alaska	Company(s):	<u>Owners, Operators or Managers</u> .Shipping Land Co.,LTD Shin Han Capital Co.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	1730 - Oily-water separating equipment	Oily water separator inoperable.
	1721 - Retention of oil on board	Oily waste incinerator and sludge pump inoperable.
	0710 - Fire prevention	Emergency fire pump inoperable with excessive exhaust leak.

Ship Name:	BUNGA ORKID LIMA	Ship Type:	Bulk Carrier
IMO Number:	9110365	Flag:	Malaysia
Date Detained:	04/11/2002	Class Society:	Det Norske Veritas
Port:	Long Beach, California	Company(s):	<u>Owners, Operators or Managers</u> Malaysia International Shipping

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	2510 - Safety and environmental policy	Vessel not in compliance with ISM code.
	0420 - Provisions	Vessel had insufficient food onboard for size of crew and duration of voyage.
	2515 - Company responsibility and authority	Company not ensuring that adequate resources are provided.
	2515 - Company responsibility and authority	Company not ensuring that appropriate corrective action is taken
	2515 - Company responsibility and authority	Company not properly verifying, reviewing and evaluating non-conformities.

Ship Name: **CARIBE C**
IMO Number: **8222410**
Date Detained: **04/24/2002**
Port: **Pensacola, Florida**

Ship Type: **General Dry Cargo Ship**
Flag: **Saint Vincent and the Grenadines**
Class Society: **Registro Italiano Navale**
Company(s): Owners, Operators or Managers
Cantieri Nord Ovest SRL
Rimorchiatori Riuniti Panfido e

Compagnia Srl,

Deficiencies: Code - Category
0740 - Pumps
1250 - Covers (hatchways
0936 - Steering gear

Description
Emergency fire pump inoperable.
Cargo hatches and numerous doors not
water/weather tiight.
#1 and #2 steering pumps leaking excessively.

Ship Name:	DIAMOND	Ship Type:	Ore/Bulk/Oil (OBO) Carrier
IMO Number:	7807859	Flag:	Liberia
Date Detained:	04/05/2002	Class Society:	Bureau Veritas
Port:	Baltimore, Maryland	Company(s):	<u>Owners, Operators or Managers</u> Seabulk Tankers Pankar Maritime S.A.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0730 - Appliances (general equipment)	Numerous fuel oil, cargo and ballast water vents on deck wasted and holed.
	1299 - Other (Load Lines)	No. 5 cargo hold starboard side forward and aft radius corners fractured.
	1299 - Other (Load Lines)	No. 1 cargo hold port side forward radius corner fractured.
	0730 - Appliances (general equipment)	Numerous holes and wastage in fire main on port and stbd side.
	1250 - Covers (hatchways)	Numerous hatch coaming brackets wasted and holed.
	1410 - Propulsion main engine	Cooling water line for #2 main service generator wasted and leaking.
	1440 - Bilge pumping	Majority of pumps in engine room leaking excessively.
	0610 - Lifeboats	Port side lifeboat winch drum wasted.
	0610 - Lifeboats	Missing 22 lifeboat rations.
	1299 - Other (Load Lines)	Support brackets for piping, ladders, conduit, cargo systems and hydraulic system wasted.
	1720 - Control of discharge of oil	Hydraulic system leaking throughout cargo block area.
	1799 - Other (MARPOL Annex I)	Previous crude oil cargo discovered in #1 cargo hold causing contamination to current cargo.

Ship Name:	FAIR LADY	Ship Type:	Bulk Carrier
IMO Number:	7625055	Flag:	Malta
Date Detained:	04/11/2002	Class Society:	Lloyd's Register of Shipping
Port:	Myrtle GroVe, Louisiana	Company(s):	<u>Owners, Operators or Managers</u> Eastern Mediterranean Maritime Ltd.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0925 - Musters and drills	Crew unable to demonstrate proficiency in fire drill.
	0720 - Fire fighting equipment	Fire hoses and nozzles in aft main deck in poor condition and not available for immediate use.

Ship Name:	KRISTINE	Ship Type:	General Dry Cargo Ship
IMO Number:	8031122	Flag:	Saint Vincent and the Grenadines
Date Detained:	04/14/2002	Class Society:	Russian Maritime Register of Shipping
Port:	Lake Charles, Louisiana	Company(s):	<u>Owners, Operators or Managers</u> Eastmar Shipping Ltd.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0630 - Launch arrangt. for survival craft	Port lifeboat davit brake system wasted and inoperable.
	0630 - Launch arrangt. for survival craft	Starboard lifeboat davit wasted.

Ship Name:	MIKAELA II	Ship Type:	Bulk Carrier
IMO Number:	8029600	Flag:	Panama
Date Detained:	04/30/2002	Class Society:	Bureau Veritas
Port:	St. Croix, USVI	Company(s):	<u>Owners, Operators or Managers</u> Mikaela Navigation Co, Ltd Sea Wind Maritime Co SA, Greece

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	1499 - Other (Prop. & Aux. Machinery)	Engineroom in unsafe condition with multiple leaks and excessive fire hazards.

Ship Name:	NEW HIROTSUKI	Ship Type:	Refrigerated Cargo Carrier
IMO Number:	9003146	Flag:	Panama
Date Detained:	04/10/2002	Class Society:	Nippon Kaiji Kyokai
Port:	Dutch Harbor, Alaska	Company(s):	<u>Owners, Operators or Managers</u> New Power Ship S.A.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0710 - Fire prevention	Bulkhead penetrations in galley do not meet fire protection rating for the space.
	0710 - Fire prevention	Doors in galley are missing self closure

Ship Name:	PACIFIC SOUND	Ship Type:	Chemical Tankship
IMO Number:	8217336	Flag:	Philippines
Date Detained:	04/12/2002	Class Society:	Nippon Kaiji Kyokai
Port:	San Francisco, California	Company(s):	<u>Owners, Operators or Managers</u> Manila Transwork Carriers Inc. Tokyo Marine Co. Ltd.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0680 - Embarkation arrangt. survival craft	Releasing mechanism on port lifeboat was inoperable.